

November 1, 1984

Douglas Aircraft Co. 3855 Lockwood Blvd. Long Beach, CA 90846

Attention: Ms. Rebecca R. Lally

Dear Ms. Lally:


I am sending you a Material Safety Data Sheet on LS 9280, your PN DPM 5310.

If you need additional information, please contact us.

Sincerely, Myers

Jim Myers

Safety & Environmental Technician



## MATERIAL SAFETY DATA SHEET

	MATERIAL SAF	EIY DAIA	SHEET	******	
Effective Date: 10-31-84					
	SECT	ION I			
			Emergency   803/74	Telephone 14-6261	No.
Address (Number, Street, City, State P.O. Box 5205, North Charleston, Sout	and ZIP Code) h Carolina 29	406			
Chemical Name and Synonyms			Trade Name and Synonyms LS 9280		
Product Type Teflon Coated Asbestos Textile			e u MANY de la company de l La companya de la companya de		
··· SÉ	CTION II - HAZ	ARDOUS IN	GREDIENTS		
Paints, Preservatives, & Solvents	%   TLV    (Units)	Alloys	and Metallic Coatings	5   %	TLV (Units)
Pigments 1		Base M	etal		1
Catalyst 1		Alloys		<u> </u>	
<u>Vehicle</u>			Metallic Coatings		<u> </u>
Solvents		Filler			<u> </u>
Addition		Others	oating or Core Flux		<u> </u>
Additives   Others	1 1	others			<u> </u>
	XTURES OF OTHE	RITOUTDS	SOLIDS OR GASES	%	TLV
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES Chrysotile Asbestos					2f/cc
Polytetrafluoethylene Resin			-	45-50	
M					
	SECTION III -	PHYSICAL	DATA		
Boiling Point (OF.)	I N/A		ic Gravity $(H_20 = 1)$		>1
Vapor Pressure (mm. Hg.)	1 1/0		t, Volatile		   N/A
Vapor Density (Air = 1)	N/A		ume (%) ating Rate		<u>  N/A</u> 
vapor bensity (Air = 1)	l N/A	I CVapor	= 1)		   N/A
Solubility in Water	Slight	1 .			1
Appearance and Odor - White solid, sl		on odor.			<u> </u>
	I IV - FIRE AND		N HAZARD DATA		
Flash Point (Method Used)		·	Flammable Limits	Le1_	l Uel
N/A Extinguishing Media - Water fog, CO2,			N/A N/PILIS		<u> </u>
Special Fire Fighting Procedures - We	<u>ear self contai</u>	ned breat	thing apparatus.	<del>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</del>	
Unusual Fire and Explosion Hazards			13 3 To 1	<del>- {}</del>	
Unusual Fire and Explosion nazards			4 3		
	(Continued or	reverse	0.23		

## SECTION V - HEALTH HAZARD DATA

SECTION V - HEALTH HAZA	IRD DATA
Threshold Limit Value - See Section II.	
Effects of Overexposure - If excessive dust is generated,	could cause asbestosis and/or cancer.
Emergency and First Aid Procedures - Teflon at high temper	ature can cause toxic fumes causing
flu like symptoms. If so, remove from exposure.	
SECTION VI - REACTIVIT	Y DATA
Unstable     Conditions to Av	oid - Contact with strong flourinating
Stability   Stable   X   agents.	
Incompatability (Materials to avoid) - Alkali metal and at	high temp, with powdered magnesium and
Hazardous Decomposition Products	aluminum.
Hazardous   May Occur     Conditions to	Avoid
Polymerization   Will Not Occur   X	
SECTION VII - SPILL OR LEAK	PROCEDURES
Steps to be taken in case material is released or spilled	- If dust is generated vacuum on yet
sweep.	1. dast is generated, vacuum or wet
Waste Disposal Method - In accordance with 29CFR 1910.1001	•
SECTION VIII - SPECIAL PROTECTION	ON INFORMATION
Respiratory Protection (Specify Type) - If dusty, NIOSH-ap	proved respirator for asbestos.
Local Exhaust - Depends on usage.	Special
Ventilation   Mechanical (General)  Protective Gloves - Cotton or leather.   Eve	Other
Other Protective Equipment - Depends on usage.	Protection
other frozective Equipment Depends on asage.	
SECTION IX - SPECIAL PREC	CAUTIONS
Precautions to be taken in handling and storing - Labels ma	ay be required. See 29CFR 1910.1001.
	-3 20 Yoqu'i oq. 300 2301K 1310.1001.
Other Precautions - Avoid creating dust. Avoid exposure to	material at high temperature without
adequate protection.	•
CONTRACTOR OF A MAN COLUMN	
MATERIAL DO 0059s	
Marien 12 Date 1	
11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
- QAUTEDNI DANGER; COI	OPATANS NEBBOODS
The second secon	A A Comment of the Co
· · · · · · · · · · · · · · · · · · ·	- DISTERNATION MAN MEDISC
<b>▼</b>	
NOW OF MAL 19/M POLITICE	
	Diane 1